


# SOCATA TB-21 TC TRINIDAD

WITH LYCOMING TIO 540 ENGINE

Item	Part Number	Description
1	LW12728	RISER STUB CYL #2
2	LW19112	EXHAUST PIPE CYL #2
3	LW19114	EXHAUST PIPE CYL #4
4	LW19116	EXHAUST PIPE CYL #6
5	LW19111	EXHAUST PIPE CYL #1 & #3
6	LW12728	EXHAUST STUB CYL #3
7	LW19115	EXHAUST PIPE CYL #5
8	LW19276	EXHAUST PIPE CROSSOVER RH
9	LW19239	EXHAUST PIPE CROSSOVER LH
10	LW19084	EXHAUST TRANSITION
11	78064	EXHAUST FLANGE
12	LW12093-5	COUPLING V BAND 2"
13	LW12093-6	COUPLING V BAND 2.25"
14	78084	GASKET V BAND 2"
15	78046	GASKET V BAND 2.25"
NS	77611	GASKET
NS	LW19107	STRUT TURBO ADJUSTABLE
NS	LW19106	TURBO MOUNT BRACKET



● Inspect transitions for internal pitting and cracks, especially at the bypass area.

☞ This part has a hot area at the elbow, inspect this area for black flaking metal and bulges.

● Inspect joints for freedom of movement and distortion.