


Exhaust Systems Engine Mounts Carb Air Boxes Shrouds • Seats • Piston • Turbine • Radial • Vintage • And More...



3eechcraft WITH P & W 985 ENGINE


Item	Part Number	Description LEFT ENGINE
1	18S9200L-9	EXHAUST SEGMENT
2	18S9200L-7	EXHAUST SEGMENT
3	18S9200L-3	EXHAUST SEGMENT
4	18S9200L-1	EXHAUST SEGMENT
5	18S9200L-23	EXHAUST SEGMENT
6	18S9204-600	COLLECTOR RING ADAPTER 9 REQ
7	189216	TAILPIPE LEFT ENGINE W/O FITTINGS
7	189208-2	TAILPIPE LEFT ENGINE C/W FITTINGS
8	18-9207-2	Intensifier Tube
-	VARIOUS	CARB HEAT MUFF PARTS
-	18S9200L-26	EXHAUST COLLAR ASSY
-	189174-610	LOWER DUCT ASSY INBOARD
-	189174-620	LOWER DUCT ASSY OUTBOARD
-	189171-600	HEAT MUFF ASSY INBOARD
-	189158	HEAT MUFF SHELL INBOARD
-	189154	HEAT MUFF SHELL INBOARD
_	189171-2	COLLAR HEAT MUFF INBOARD
-	189171-4	COLLAR HEAT MUFF INBOARD
-	189171-6	COLLAR HEAT MUFF INBOARD
_	189171-8	COLLAR HEAT MUFF INBOARD
_	105798-14	CLAMP HEAT MUFF INBOARD
-	105798-17	CLAMP HEAT MUFF INBOARD
-	189171-610	HEAT MUFF ASSY OUTBOARD
-	189165	HEAT MUFF SHELL OUTBOARD
-	189163	HEAT MUFF SHELL OUTBOARD
-	189171-10	COLLAR HEAT MUFF OUTBOARD
-	189171-12	COLLAR HEAT MUFF OUTBOARD
-	105798-18	CLAMP HEAT MUFF OUTBOARD
-	105798-21	CLAMP HEAT MUFF OUTBOARD
-	SOL3503	GASKETS NO BLOW

• Acorn Welding has many years of experience with round engines. There are advantages to sending us your complete system when an overhaul or repair is required. It will ensure better joint integrity, a stress free system plus the inner cowling will stay cleaner from combustion by-products. With our will stay cleaner from combustion by-products. system there should be no need for repairs between engine changes. We maintain standard factory sizes so new factory



Item	Part Number	Description RIGHT ENGINE
-	18S9200R-601	EXHAUST ASSY
1	18S9200R-26	EXHAUST SEGMENT
2	18S9200R-11	EXHAUST SEGMENT
3	18S9200R-7	EXHAUST SEGMENT
4	18S9200R-4	EXHAUST SEGMENT
5	18S9200R-1	EXHAUST SEGMENT
6	18S9200R-27	EXHAUST SEGMENT
7	189216-1	TAILPIPE RIGHT ENGINE
8	18S9204-600	COLLECTOR RING ADAPTER 9 REQ
9	18-9207-2	Intensifier Tube
-	189175-621	LOWER DUCT ASSY INBOARD
-	198175-611	LOWER DUCT ASSY OUTBOARD
-	189186-601	HEAT MUFF ASSY OUTBOARD
-	189177	HEAT MUFF SHELL OUTBOARD
-	189182	HEAT MUFF SHELL OUTBOARD
-	189186-2	COLLAR HEAT MUFF OUTBOARD
-	189186-4	COLLAR HEAT MUFF OUTBOARD
-	105798-18	CLAMP HEAT MUFF OUTBOARD
-	105798-21	CLAMP HEAT MUFF OUTBOARD
-	189186-661	HEAT MUFF ASSY INBOARD
-	189181	HEAT MUFF SHELL INBOARD
-	189180	HEAT MUFF SHELL INBOARD
_	189186-6	COLLAR HEAT MUFF INBOARD
_	189186-8	COLLAR HEAT MUFF INBOARD
_	189186-10	COLLAR HEAT MUFF INBOARD
-	189186-12	COLLAR HEAT MUFF INBOARD
-	105798-14	CLAMP HEAT MUFF INBOARD
-	105798-17	CLAMP HEAT MUFF INBOARD
-	SOL3503	GASKETS NO BLOW

• Acorn Welding has many years of experience with round engines. There are advantages to sending us your complete system when an overhaul or repair is required. It will ensure better joint integrity, a stress free system plus the inner cowling will stay cleaner from combustion by-products. With our system there should be no need for repairs between engine changes. We maintain standard factory sizes so new factory



(toll free) 1-888-388-8803 1-780-447-5955 Fax: 1-780-447-5980 parts@acornwelding.com sales@acornwelding.com www.acornwelding.com