

STINSON SM1B

WITH LYCOMING 785 SR9 ENGINE

Item	Part Number	Description
1		Exhaust System

- The stack assembly and flanges are most likely mild steel and not stainless steel. Inspect for thinning and corrosion.

